

4 选择标准

		VEGAPULS 67	VEGAPULS SR 68	VEGAPULS 68	VEGAPULS 69
容器	小型到中型容器	●	●	●	●
	中型到大型容器	-	●	●	●
	大型容器	-	-	●	●
	很大的容器	-	-	●	●
过程	简单的过程条件	●	●	●	●
	最艰难的过程条件	-	●	●	-
安装	螺纹接头	-	●	●	●
	法兰接头	●	●	●	●
	龙门框	●	-	-	●
天线	旋转支架	●	●	●	●
	塑料天线	●	-	-	●
	喇叭形天线	-	●	●	●
	用金属封装的透镜天线	-	-	-	●
	抛物线形天线	-	●	●	-
对行业特种用途的适用性	建筑, 石材, 土壤	●	●	●	●
	化学	●	●	●	●
	能源制造	-	●	●	●
	食品	●	●	●	●
	金属开采	●	●	●	●
	海上作业	-	●	●	-
	纸品	●	●	●	-
	石化	-	●	●	-
	医药	-	●	●	-
	环保和回收	●	●	●	-
	水泥制造	●	●	●	●